



Ground the panel with a solder terminal at one of the panel mounting holes.

To Point "C" Jack Panel

C

C (GND)

To Power Supply

AA

To C22 on Jack Panel

QQ (-9V)

PP (+9V)

To Power Supply

Micro Sample & Hold Component Designators

(R6 and R94 are 510 ohm)

SLMS PCB Kludge Connections

Micro S&H PCB Connections

SLMS PCB Connections

Jack Panel Connections

= 1N914 or equiv.